

ReleaseOrderPkg ID: SCGCQ01167961 [Open In CQWeb](#) [Download](#)

Headline: SAS3 Phase 13 - External Web Posting for invader/Fury Boards

Package\_Type: SAS3 Web Posting Package

Tier Account: LSI Generic

Package\_Version: SAS3 1.0

Date Generated: Aug 25, 2016

- [SCGCQ01141661 - GCA Release: IRCU\\_MPT\\_GEN3\\_Phase13.0 - 14.00.00.00](#)
- [SCGCQ01141636 - GCA Release: FLASH\\_MPT\\_GEN3\\_Phase13.0 - 14.00.00.00](#)
- [SCGCQ01141489 - GCA: BIOS\\_MPT\\_GEN3\\_Phase13.0 - 8.31.00.00 BIOS](#)
- [SCGCQ01141463 - GCA: SAS3 IT/IR UEFI Boot Services Driver and HII utility v15.00.00.00](#)
- [SCGCQ01140808 - GCA Release: SAS3FW\\_Phase13.0 - 13.00.00.00 Firmware IT IR Release](#)
- [SCGCQ01137086 - Linux Phase 13 GCA release.](#)
- [SCGCQ01135878 - FreeBSD SAS3 IT/IR: mpt driver GCA release with v14.00.00.00](#)
- [SCGCQ01108847 - GCA: LSI SAS3 v2.51.15.00 Phase 13 Windows Driver](#)
- [SCGCQ00179278 - SAS2 NVDATA Parser Tool Version 09.00.00.00](#)

GCA Release (SCGCQ01141661) - SAS3IRCU - 14.00.00.00



ReleaseOrderID: SCGCQ01141661 [Open In CQWeb](#) [Download](#)

Headline: GCA Release: IRCU\_MPT\_GEN3\_Phase13.0 - 14.00.00.00

Release Version: 14.00.00.00

Product Org: SCS

Product Gen: SAS3

Product Family: SAS3\_Applications

UCM Project: IRCU\_MPT\_GEN3\_Phase13.0

Release Type: GCA

UCM Stream: IRCU\_MPT\_GEN3\_Phase13.0\_Rel

Owner: buildsvc

Release Baseline: IRCU\_MPT\_GEN3\_Phase13.0-2016-07-21-14.00.00.00\_REL\_1469100659@  
ISAS2

Release Date / Time: 25-JUL-16

Release Type: GCA

GCA Release (SCGCQ01141636) - SAS3FLASH - 14.00.00.00



ReleaseOrderID: SCGCQ01141636 [Open In CQWeb](#) [Download](#)

Headline: GCA Release: FLASH\_MPT\_GEN3\_Phase13.0 - 14.00.00.00

Release Version: 14.00.00.00

Product Org: SCS

Product Gen: SAS3

Product Family: SAS3\_Applications

UCM Project: FLASH\_MPT\_GEN3\_Phase13.0

Release Type: GCA

UCM Stream: FLASH\_MPT\_GEN3\_Phase13.0\_Rel

Owner: buildsvc

Release Baseline: FLASH\_MPT\_GEN3\_Phase13.0-2016-07-21-14.00.00.00\_REL\_1469099330@  
ISAS2

Release Date / Time: 22-JUL-16

Release Type: GCA

GCA Release (SCGCQ01141489) - BIOS - 8.31.00.00



ReleaseOrderID: SCGCQ01141489 [Open In CQWeb](#) [Download](#)

Headline: GCA: BIOS\_MPT\_GEN3\_Phase13.0 - 8.31.00.00 BIOS

Release Version: 8.31.00.00

Product Org: SCS

Product Gen: SAS3

Product Family: SAS3\_BIOS

UCM Project: BIOS\_MPT\_GEN3\_Phase13.0

Release Type: GCA

UCM Stream: BIOS\_MPT\_GEN3\_Phase13.0\_Main\_Dev

Owner: shivanis

Release Baseline: BIOS\_MPT\_GEN3\_Phase13.0\_Main\_Dev\_2016-07-21@  
ISAS2

Release Date / Time: 29-JUL-16

Release Type: GCA

GCA Release (SCGCQ01141463) - UEFI BSD - 15.00.00.00



ReleaseOrderID: SCGCQ01141463 [Open In CQWeb](#) [Download](#)

Headline: GCA: SAS3 IT/IR UEFI Boot Services Driver and HII utility v15.00.00.00

Release Version: 15.00.00.00

Product Org: SCS

Product Gen: SAS3

Product Family: SAS3\_BIOS

UCM Project: UEFIBSDHII\_MPT\_GEN3\_Phase13.0

Release Type: GCA

UCM Stream: UEFIBSDHII\_MPT\_GEN3\_Phase13.0\_Rel

Owner: shivanis

Release Baseline: UEFIBSDHII\_MPT\_GEN3\_Phase13.0\_Rel\_2016-07-21@ISAS2

Release Date / Time: 29-JUL-16

Release Type: GCA

GCA Release (SCGCQ01140808) - Firmware - 13.00.00.00



ReleaseOrderID: SCGCQ01140808 [Open In CQWeb](#) [Download](#)

Headline: GCA Release: SAS3FW\_Phase13.0 - 13.00.00.00 Firmware IT IR Release

Release Version: 13.00.00.00

Product Org: SCS

Product Gen: SAS3

Product Family: SAS3\_Controller\_FW

UCM Project: SAS3FW\_Phase13.0

Release Type: GCA

UCM Stream: SAS3FW\_Phase13.0\_Rel  
Owner: buildsvc  
Release Baseline: SAS3FW\_Phase13.0-2016-07-20-13.00.00.00\_REL\_1469005660@\SAS\_CTRL\_FW  
Release Date / Time: 29-JUL-16  
Release Type: GCA

GCA Release (SCGCQ01137086) - Linux Driver - RHEL5-6\_SLES10-11 - 14.00.00.00-1



ReleaseOrderID: SCGCQ01137086 [Open In CQWeb](#) [Download](#)  
Headline: Linux Phase 13 GCA release.  
Release Version: 14.00.00.00-1  
Product Org: SCS  
Product Gen: SAS3  
Product Family: SAS3\_Drivers  
UCM Project: LINUX\_RH\_SL\_OEL\_CTX\_MPT\_GEN3\_PHASE13.0  
Release Type: GCA  
UCM Stream: LINUX\_RH\_SL\_OEL\_CTX\_MPT\_GEN3\_PHASE13.0\_Dev  
Owner: vt017885  
Release Baseline: LINUX\_RH\_SL\_OEL\_CTX\_MPT\_GEN3\_PHASE13.0\_Dev\_2016-08-11@  
\\SAS2  
Release Date / Time: 16-AUG-16  
Release Type: GCA

GCA Release (SCGCQ01135878) - Free BSD Driver - 14.00.00.00-1



ReleaseOrderID: SCGCQ01135878 [Open In CQWeb](#) [Download](#)  
Headline: FreeBSD SAS3 IT/IR: mpt driver GCA release with v14.00.00.00  
Release Version: 14.00.00.00-1  
Product Org: SCS  
Product Gen: SAS3  
Product Family: SAS3\_Drivers  
UCM Project: FREEBSD\_MPT\_GEN3\_PHASE13.0  
Release Type: GCA  
UCM Stream: FREEBSD\_MPT\_GEN3\_PHASE13.0\_Rel  
Owner: srreddy  
Release Baseline: FREEBSD\_MPT\_GEN3\_PHASE13.0\_Rel\_2016-07-13\_v14.00.00.00@  
\\SAS2  
Release Date / Time: 22-JUL-16  
Release Type: GCA

GCA Release (SCGCQ01108847) - Windows Driver - 2.51.15.00



ReleaseOrderID: SCGCQ01108847 [Open In CQWeb](#) [Download](#)  
Headline: GCA: LSI\_SAS3 v2.51.15.00 Phase 13 Windows Driver  
Release Version: 2.51.15.00  
Product Org: SCS  
Product Gen: SAS3  
Product Family: SAS3\_Drivers  
UCM Project: WINDOWS\_MPT\_GEN3\_PHASE13.0  
Release Type: GCA  
UCM Stream: WINDOWS\_MPT\_GEN3\_PHASE13.0\_MAIN\_DEV  
Owner: ssamant  
Release Baseline: WINDOWS\_MPT\_GEN3\_PHASE13.0\_SDV\_issue\_Int\_2016-08-17@  
\\SAS2  
Release Date / Time: 19-AUG-16  
Release Type: GCA

Windows Driver Defects Fixed (11):

Defect ID: SCGCQ01092212

Headline: SAS3 Windows Driver:- Drive enumeration or Drive discovery failed from Intruder/Cutlass card on Windows\_8.1\_x86 OS

Description Of Change: The inconsistency in INF file is fixed. In INF [SourceDisksFiles.amd64] section renamed to just [SourceDisksFiles] so it matched up with [SourceDisksNames].

Issue Description: Config details:-

OS:- Windows 8.1 x86 client  
HBA:- Intruder/Cutlass  
Driver :- 2.51.13.00

HBA --> Expander--> Enclosure (SAS drives)  
--> Jbod (SATA & SAS drives)

1. Installed Intruder/Cutlass card in the system and flashed latest phase13 FW on the card.
2. System booted to Windows 8.1 x86 OS, and installed latest Phase-13 windows 8.1 x86 driver. (win8.1\_x86 driver)
3. driver installed successfully and HBA discovered from the OS.
4. Connected enclosure and a JBOD as shown above.
5. Drive discovery failed, unable to list the drives from device manager.
6. Drivers were listed successfully from FW ( uart:- pl status output)
7. While rebooting the system, From BIOS post Drivers discovered attached to HBA.

Same is working with Fury/invader card.

- Steps To Reproduce:
1. Installed Intruder/Cutlass card in the system and flashed latest phase13 FW on the card.
  2. System booted to Windows 8.1 x86 OS, and installed latest Phase-13 windows 8.1 x86 driver. (win8.1\_x86 driver)
  3. driver installed successfully and HBA discovered from the OS.
  4. Connected enclosure and a JBOD as shown above.
  5. Drive discovery failed, unable to list the drives from device manager.
  6. Drivers were listed successfully from FW ( uart:- pl status output)
  7. While rebooting the system, From BIOS post Drivers discovered attached to HBA.

Defect ID: SCGCQ01095525

Headline: Remove the logging of Null SRB context when the SMID is staticMsg1SMID.

Description Of Change: Static Message1 is not part of tracking array so any command sent using static message 1 should not have any SRB to check from tracking array.

Issue Description: TUR ready command as part of Lun Reset is sent by static msg1 , in max cases this commands times out resulting unnecessary logging when we get the address reply for it when LUn reset sent to FW.

Steps To Reproduce: When the TUR times out , you can see in the rtracce RT\_EVID\_ERROR\_COMPLETE\_NULL\_SRB is being logged and in windows system event MPI\_LOG\_NULL\_SRB\_BAD\_CONTEXT is always logged.

Defect ID: SCGCQ01107003

Headline: SAS3 Windows Driver : Windows OS crashes while running IOs and TMs

Description Of Change: when we got through the Complete IO routine because of LUN TUR timer call back , the code was not returning from completeIO therefore accessing the NULL exSRB.

Issue Description: Config details

Server :- DELL T7600  
OS:- Windows 2016 server  
Driver :- 2.51.14.00  
HBA:- Cutlass

>>Installed latest Driver and successfully discovered all the drives attached to the HBA.  
>> Started IOs on the bare drives, kept running one hour.  
>>Then triggered TMs in the background.  
>>after two iterations of TMs , system crashed with "Driver\_IRQL\_not\_less\_or\_equal(LSISAS3.sys)"

**Defect ID:** SCGCQ01162603

**Headline:** To fix SDV issue

**Description Of Change:** all reported errors addressed.

**Issue Description:** To fix SDV issue

**Steps To Reproduce:** Please run the SDV to get the

**Description Of Change:** Modified the loop as follows.

**Issue Description:** This issue will need to be CSET back to LSI\_SAS2 and LSI\_SAS3.

The below loop as implemented will stop advancing the MFABuffer pointer once it finds a LUN reset on another LUN. The loop will still run to the end, but MFABuffer will not be advanced beyond that entry so no following entries will be checked and IOs could be pending on that LUN and be missed as a result.

This code is in reset.c module ProcessLunTargetReset (ca\_util.c function ProcessTmResetReply in older drivers).

**Steps To Reproduce:** N/A

**Description Of Change:** Added throttling to specific RTTRACE events to prevent them from overrunning the log buffer during some failure scenarios involving ResetActive being set.

**Steps To Reproduce:** Use a Windows kernel debugger to set DeviceExtension->ResetActive to 1.  
Run an IO load on the driver.  
Collect the RTTRACE logs from the driver to see that it has been overrun with lots of these events.

**Description Of Change:** Moved setting of Saved SRB to after the pointers have been changed.

**Steps To Reproduce:** N/A

**Defect ID:** SCGCQ01095072

**Headline:** Srb and SrbExt should not be accessed after completing Srb

**Description Of Change:** Moved capture of data for RTTRACE event to occur before the SRB is completed back to StorPort.

**Issue Description:** In ca\_int.c, in the section that is completing Success IOs, there are RTTRACE logs being created which access the Srb and SrbExt pointers after the Srb has been completed. We have learned from MR that if processing is interrupted at just the right time, Storport can reuse that Srb (modifying many elements) and those accesses will be getting data for the new Srb and not the Srb that is being completed. The RTTRACE code should be executed before the call to StorPortNotification(RequestComplete).

Defect noticed during code inspection.

Note that these RTTRACE logs only execute when tracing for the main IO path is enabled, which it is disabled in all production drivers for performance.

**Steps To Reproduce:** N/A

**Defect ID:** SCGCQ01115185

**Headline:** Second UAR received on LUN reset TUR while UAR already in-progress aborts causing lost IO SRB

**Description Of Change:** Added a check when kicking-of the UAR state machine to handle a new UAR to verify its current state. If the state machine is already running, the UAR is rejected and not handled. This allows the current UAR to finish completion and avoids losing the associated SRB, which allows the system to recover cleanly.

**Issue Description:** When a UAR is detected on an IO reply from a LUN the driver starts the UAR state machine to handle the UAR. If StorPort sends a LUN reset to the same LUN while the UAR state machine is running, and the LUN reset TUR also comes back with a UAR, the driver will restart the UAR state machine from the beginning abruptly. This results in the original IO SRB getting lost and never completed. This in-turn causes StorPort to enter into an infinite LUN reset loop on that LUN, and all IOS will be blocked.

**Steps To Reproduce:** Run cable breaker every 5 seconds while also running a heavy IO load across topology with lots of disks (55+). May require an hour or little longer to reproduce.

**Defect ID:** SCGCQ01058006

**Headline:** Ventura Windows Driver: System crashes while running IOs on storage pools along with TMs

**Description Of Change:** Replaced all polling of the ISR when running under ISR context with a delay to allow each ISR thread time to process its own IOs.

**Issue Description:** Configuration details:-

OS:- Windows server 2016 TP4  
HBA:- Ventura  
FW:- 00.250.65.00  
Driver:- 2.60.16.00

Server -> HBA (ventura) --> JBOD attached NVME drive  
--> JBOD attached NVME drive  
--> cobra expander --> Super micro 12G Enclosure  
--> Dataon 12G Enclosure

>>Ventura HBA was flashed with latest FW (00.250.65.00) and installed in the system.  
>>Installed supported Driver in the OS (2.60.16.00).  
>>Discovered all the drives connected to the HBA in the OS.  
>>created Storage pools from Windows server manager.  
>>Created four storage pools (storage pool1 --> sas drives ( Virtual disk1- 6TB), Storage pool2 --> sas drives ( virtual disk2 - 3TB), Storage pool3 --> sas drives (virtual disk3 - 5TB), Storage pool4 --> NVME drives - (virtual disk4 - 750GB) )  
>>Created NTFS File systems on all the four Virtual disks from windows Disk management.  
>> started IOs on all the File systems using IOMETER tool. (Random IOs reads & writes)  
>>In the background started triggering TMs ( target resets, lun resets, & diag resets) Using a SAL script.  
>>After 10 mins of the Test, system crashed with "DPC\_Timeout" and rebooted.

**Steps To Reproduce:** Configuration details:-

OS:- Windows server 2016 TP4  
HBA:- Ventura  
FW:- 00.250.65.00  
Driver:- 2.60.16.00

Server -> HBA (ventura) --> Enclosure attached NVME drive  
--> Enclosure attached NVME drive  
--> cobra expander --> Super micro 12G Enclosure  
--> Dataon 12G enclosure

>>Ventura HBA was flashed with latest FW (00.250.65.00) and installed in the system.  
>>Installed supported Driver in the OS (2.60.16.00).  
>>Discovered all the drives connected to the HBA in the OS.  
>>created Storage pools from Windows server manager.  
>>Created four storage pools (storage pool1 --> sas drives ( Virtual disk1- 6TB), Storage pool2 --> sas drives ( virtual disk2 - 3TB), Storage pool3 --> sas drives (virtual disk3 - 5TB), Storage pool4 --> NVME drives - (virtual disk4 - 750GB) )  
>>Created File systems on all the four Virtual disks from windows Disk management.  
>> started IOs on all the File systems using IOMETER tool.  
>>In the background started triggering TMs ( target resets, lun resets, & diag resets)  
>>After 10 mins of the Test, system crashed with "DPC\_Timeout" and rebooted.

**Defect ID:** SCGCQ01145845

**Headline:** Device Driver INF Verification Test (Certification) fails with error on all OSs Win10 client/server HLK

**Description Of Change:** Both Production and Inbox INF files are modified .

**Issue Description:** Windows INF test Device Driver INF Verification Test (Certification) fails with error on all OSs Win10 client/server HLK  
UserText=The inf C:\Windows\Infoem0.inf had an error at line 357.  
This line is missing the double quote (") at the end of the line. Adding one to continue processing.CA="8651479" LA=8651604

Error gets filtered on earlier OS's below win 8.1 but expires in October.  
Error does not occurs with phase 9 driver used for Cutlass installs.

**Steps To Reproduce:** Run the INF support test in an HLK environment on win 10, win server 2016

Windows Driver Enhancements Implemented (1):

**EnhancementRequest ID:** SCGCQ01108849

**Headline:** Add PCI IDs for NGM HBA330 Controllers

**Description Of Change:** Both Production and Inbox INF files have been updated.

Alpha Release (SCGCQ00179278) - SAS2PARSER - 09.00.00.00

ReleaseOrderID: SCGCQ00179278 [Open In CQWeb](#) [Download](#)

Headline: SAS2 NVDATA Parser Tool Version 09.00.00.00

Release Version: 09.00.00.00

Product Org: SCS

Product Gen: SAS2

Product Family: SAS2\_Applications

UCM Project: SAS2PARSER

Release Type: Alpha

UCM Stream: SAS2PARSER\_Rel

Owner: sbakthav

Release Baseline: SAS2PARSER\_2\_18\_2011\_v9.00.00.00\_REL@SAS2

Release Date / Time: 18-FEB-11

Release Type: Alpha