

IPMI Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPM-TF/LN4F/LN6TF
Release Version	01.00.14
Build Date	7/27/2021
Previous Version	01.00.03
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Set BMC boot firmware flash to use 3byte mode.2. Improved internal flow of BIOS update.3. Improved compatibility with provisioning rot_checker script 2021Q2.4. Modified Virtual CD-ROM help content.5. Upgraded BIOS firmware and refactored the codes.
New features	<ol style="list-style-type: none">1. Changed location name on NIC page (AIOM->System Slot A#, PCIE-> System Slot #) to use location name from [Chassis/1/Thermal] so that when thermal name includes [AIOM], the location field shows [System Slot A#], when thermal name includes [AOC], the location field shows [System Slot #], and when thermal name includes [AOCUR_NIC], the location field shows [System Slot 0].

Fixes	<ol style="list-style-type: none">1. Fixed mismatch between AOC M.2 devices sensor name and Supermicro_X12 Temp Sensor Naming Guildline_1.0f.2. Fixed unavailability of AOC M.2 devices sensor on BMC web interface sensor list.3. Fixed behavior on Port Page when Port is turned OFF and ON.4. Fixed problem of error message appearing after modifying web port.5. Fixed problem of system hanging and losing BMC connection after updating CPLD from WebGUI or SUM.6. Fixed issue with RADIUS server address input.7. Fixed problem of the result of test case 255 displaying "stoi: no conversion".8. Fixed mismatch between IPMI sensor GUI NIC ASIC naming and X12 temperature sensor guildline_1.0f.9. Fixed WebGUI login after a session reset.10. Fixed missing AOC GPU/Network info & GPU/Network Temp Sensor in IPMI WebGUI.11. Fixed problem of evidence blocking fwUP in 2021-07 release.12. Fixed failure of disconnection message to appear exactly when performing IPMI firmware update on web.
--------------	---

Release Notes from Previous Release(s)

01.00.03 (4/21/2021)

1. Fixed failure to add IPv6 link local address, problem of turning off "Web port" automatically turning off other ports at the same time, failure of IP Address to allow IPv6 format on "IP Access Control" page, problem of Unlock/Select button being enabled for Virtual CDROM/SMTP Password/RADIUS/DDNS (system lockdown mode), failure of Redfish SimpleUpdate API for BIOS firmware update, missing Storage page on IPMI, NVMe blink behavior after hot swap and ejection/insertion, mismatch of System Board Power Consumption Graph X-axis "Time Stamp" with system current time, one 0xDC event description, ability to configure DNS Server IP/DNS Server2 IP on Network page (system lockdown mode), inability to remove selected file on the "Floppy Disk" due to out of frame icon, ability to configure Network (IPv4/SSL cert/SSDP/DDNS) and HEL (Warning!) check box for RADIUS user (Operator Privilege), ability to configure IPv4/DDNS/HEL (Warning!) check box for Local/RADIUS user (User Privilege), problem of Note box and hit message overlapping and appearing out of frame on SSDP page, and sorting result of "Total duration" field (Task list).
2. Fixed problem of Component information section under CarrierBoard IPMI Web System Component Overview page, malfunction of HTTPS redirect if not on default HTTP/HTTPS ports, problem of downloaded Excel file containing event logs when no category is selected, problem of DIMM Temp showing as N/A during ON/OFF testing, and failure of SUM 2.5.2 (210112) MountIsoImage.
3. Fixed abnormality of CPU Max Speed on IPMI CPU page, failure of IPMI sensor reading of all AOCs on all riser slots to show, problem of Network Page Health Status displaying as Critical with non-sensor AIOM card, problem of MEL order flipping after modifying IP Access Control, problems of duplicate MEL entries for enabling/disabling IP Access Control appearing and extra rule adding an entry after disabling, and missing TelemetryService value in SupportedCollectionFunctions.

0.31.04 (3/5/2021)

1. Enabled erase NAND partition feature.
2. Enhanced i2cRead PSU 1byte by 1byte.
3. Refactored the NCT6683 discovery process.
4. Added new PROCHOT logic.
5. Added support for DCPMM temperature sensor reading to work with ME version SPS_E5_04.04.051.0 or newer.
6. Added support for BIOS boot config recovery.
7. Fixed problem of IPMI SEL log showing "SPI Channel attack prevented" SEL log when AC is on, issue with add-on card thermal reading, Expander Temp sensor reading, ability of IPMI Web - Virtual Media - Virtual CD-ROM to import invalid symbol for input option, incorrect CreateVDActionInfo attribute value in Redfish for Marvell NR2241-B, and mismatch between IPMI Web System - Component Info - Product Info item display order and spec.
8. Fixed missing BIOS recovered from golden image event log in SEL, problem of configure parameter error occurring when creating RAID on WebGUI Marvell NR2241-B, problem of error message appearing when turning on NTP, and conflict between definitions in two sensor documents.
9. Fixed failure of hardware monitor check, problem of Node 1 front panel UID LED staying solid on after updating PDB CPLD firmware through IPMI WebGUI, failure of SYS-120C-TN10R FTU test, error of IPMI Web - System - Component Info - Overview - CPU health status, and ability of IPMI Web - Virtual Media - Virtual CD-ROM to import invalid symbols for input option.
10. Fixed download evidence file name, malfunction of IPMI Web eject and insert functions, abnormality of the "NTP Enable/Daylight Savings Time" button UI, missing Virtual Raid information on Logical View page, problem of Close/Enable system lockdown hanging at confirmation window, inability to test SATC Redfish automation, missing disk information from IPMI WebGUI for SK Hynix PE8010, problem of downloaded Excel file containing event log when no category is selected, enabled

button for operator user for SSDP and SSL Certificate, mismatch of downloaded sensor file with WebGUI, problem of severity of "System NIC (0) IPv6 IP Change" appearing as "OK" instead of "Warning", problem of "PDSlotx not present - Deassertion" event incorrect" showing when assertion passes under the BMC WebUI_Health Event Log on the X12SPL, problem of "PDSlotx not present - Deassertion" event incorrect" showing when assertion passes under the BMC WebUI_Health Event Log on the X12SCZ-TLN4F, mismatch of RAID VD strip block size, reversed vendor/device/sub-vendor/sub-device IDs, the DCPMM naming by changing "DCPM" to "PMEM" in IPMI sensor reading.

11. Fixed problem of garbage value displaying in health event logs for Marvel RAID card, ability of IPMI Web - Virtual Media - Virtual CD-ROM to import invalid symbols for input option, problem of unauthorized process (sshd in /sbin/) accessing critical data (platform.conf) while modifying port, problem of modification button for ADMIN user being enabled in system lockdown, issues with SYS-610U-TNR PVT Burn-in, missing domain for Active Directory Binding, problem of save returning "ERROR:A general..." when the SNMPv3 is "OFF", and problem of BMC randomly hanging on factory default.

12. Fixed failure of Remote Console Preview monitor function with User privilege account.

13. Fixed failure of 14 cases in BIOS ECO Robot automation test, problem of POST showing BMC unresponsive warning after AC cycle, missing related information for "Generate evidence / Download evidence" in help content, inability to retry "Download Evidence" and missing alert to mention it before BMC unit reset, and X12DPG-AR IPMI Sensors.

14. Fixed failure of IPMI Hardware Monitor, failure of "Generate Evidence" to translate to simplified Chinese and Japanese, inability of SYS-730A-I BMC to show NVMe SSD sensor reading and missing fan speed control, CPU1's VRM fan curve, P1_DIMM fan curve, disabling of elements for account privileges, NVMe information error in the IPMI GUI, AOC NIC sensor naming, and duplicated sensor name for AOC NIC.

15. Fixed problem of "U2_SSD1 Temp" sensor dropping during ON/OFF, malfunction of physical view page button with operator privilege user, problem of IPMI LAN status display disconnecting when VLAN setting is enabled, presence of "Delete" function when ADMIN (Network Privileges: Administrator) is locked, problem of using full-width characters at "SNTP" returning "Oops! Something went wrong..." error, problem of using full-width characters at "Redfish" returning "Oops!" error and incorrect tips, problem of using full-width characters at "ROCommunity" and "RWCommunity" returning "ERROR:A general..." on SNMP page, problem of using full-width characters at "User name", "Auth Key", or "Private Key" returning "ERROR:A general..." and incorrect tips on SNMP page, problem of using space at "Systelog Server" getting different behavior, problem of using full-width characters at "SMTP Server", "Port Number", and "User name" getting different behavior, display of power supply information, problem of KCS error occurring during on/off test, BMC IP issue under failover mode after firmware update, display of CPU Speed under MiB Browser, problem of 404 occurring for GET <https://IP/redfish/v1/Chassis/1/PCleDevices/PCleSSD0>, and inability of "BMC hostname" to save changes even if the request is successfully set at Dynamic DNS.

16. Fixed problem of X12DHM IPMI omitting GPU sensor, failure of IPMI to report BIOS Golden info, failure of Web UI -- SNMPv1 Textfield error checking, failover of LAN interface mode, problem of iKVM screen hanging when dedicated changes to shared, failure of the CPU speed reaching the Max Speed in MHz, problem of Syslog sending Daemon logs from BMC, missing storage function on IPMI WebGUI, and information displayed when "Virtual Media Port" is turned off.