

BIOS Release Notes

TITLE

SUBJECT: MZU3-MG0 BIOS Release Notes version R25_F20
System: CSC403-00,MZU3-MG0-000,XV23-ZU0-AAJ1-000,G494-ZU0-AAP1-000,
W793-ZU0-LA71-000

About This Release

Build Date: 2026/09/03
BIOS Checksum: 0x67033CF6 (64M)
Release Owner: Nelson.Lin

BIOS Components/Contents

Processor stepping(s) supported: AMD Turin / Genoa Processors
System hardware configurations supported: MZU3-MG0-000
PCB Version: 3.x
Microcode updates versions:

CPUID	Family	Microcode Update ID
Turin A0	Family 1Ah Model 00h-0Fh	0x0B00004D
Turin B0	Family 1Ah Model 00h-0Fh	0x0B001016
Turin C0	Family 1Ah Model 00h-0Fh	0x0B002032
Turin C1	Family 1Ah Model 00h-0Fh	0x0B002175
Turin Dense A0	Family 1Ah Model 00h-0Fh	0x0B10000F
Turin Dense B0	Family 1Ah Model 00h-0Fh	0x0B101066

IPMI support:
AMI Kernel version: 5.35_0ACST_PI1.0.0.B_025
AGESA PI version: TurinPI 1.0.0.B
OPROM version:

OPROM	Version
AST2600	1.13.00

Installation Notes

IMPORTANT NOTES:

1. Please extract the MZU3-MG0_R25_F20.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.

BIOS Release Notes

2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Flash script for bios update:
 - 4.1 For AMD EPYC 9004 series CPU, execute f_GtoT.nsh
 - 4.2 For AMD EPYC 9005 series CPU, execute f.nsh
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. For AMD EPYC 9004 series CPU:
 - 3.1 Enter \Tool\WIN\afuwin32 and execute f_GtoT.bat for Windows 32bit.
 - 3.2 Enter \Tool\WIN\afuwin64 and execute f_GtoT.bat for Windows 64bit.
4. For AMD EPYC 9005 series CPU:
 - 4.1 Enter \Tool\WIN\afuwin32 and execute f.bat for Windows 32bit.
 - 4.2 Enter \Tool\WIN\afuwin64 and execute f.bat for Windows 64bit.
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

R25

1. [Feature] Update AGESA 1.0.0.B.
2. [Feature] Update DDR manufacturer information.
3. [Security] CVE-2024-36357, CVE-2024-36350, CVE-2025-29941, CVE-2025-48504, CVE-2025-58771, CVE-2025-58772, CVE-2025-58773, CVE-2025-58774, CVE-2026-0004, CVE-2026-0435, CVE-2026-0454, CVE-2026-0480, CVE-2026-0893, CVE-2026-28245, CVE-2026-28246, CVE-2026-28247, CVE-2026-28248, CVE-2026-40668, CVE-2026-40670.

R24

1. [Feature] Update DDR manufacturer information.
2. [Feature] Add Above 4G Resource configuration item.
3. [Feature] Support 2K IO Resources Support item displayed.
4. [Feature] Enhance system stability.
5. [Security] CVE-2026-33197, CVE-2026-33198.

BIOS Release Notes

R23

1. [Feature] Update AGESA 1.0.0.A
2. [Feature] Enhance Redfish.
3. [Feature] Enhance system stability.
4. [Security] CVE-2025-0027, CVE-2025-11187, CVE-2025-15467, CVE-2025-29940, CVE-2025-52535, CVE-2025-52537, CVE-2025-54501, CVE-2025-54502, CVE-2025-54503, CVE-2025-54504, CVE-2025-54506, CVE-2025-54508, CVE-2025-62620, CVE-2025-62621, CVE-2025-68160, CVE-2025-69418, CVE-2025-69419, CVE-2025-69421, CVE-2026-22795, CVE-2026-22796.

R22

1. [Feature] Update Genoa AGESA 1.0.0.H.

R21

1. [Feature] Optimize IO Resource for R9700.

R20

1. [Feature] Update AGESA 1.0.0.9
2. [Feature] Enhance Redfish.
3. [Feature] Enhance PLX function.
4. [Security] CVE-2023-45236, CVE-2023-45237, CVE-2025-54502, CVE-2025-54507, CVE-2025-54510, CVE-2025-61971, CVE-2025-61972, CVE-2025-62626.

R19

- 1.[Feature] Update VR to version: G1F9.

R18

1. [Feature] Add system W793-ZU0-LA71-000.
2. [Feature] Update Inventory v21.

R17

1. [Feature]: Update AGESA 1.0.0.7
2. [Feature]: Support HDD OPAL
3. [Security]: CVE-2025-0033, CVE-2025-3770, CVE-2025-29943.

R16

1. [Fix] Fix Switch BIOS1 BIOS2 cmd failed issue.

BIOS Release Notes

R15

1. [Fix] Fix TO25-ZU4-AA01 OCP read present issue

R14

- 1.[Feature] Update AGESA 1.0.0.6.
- 2.[Security]: CVE-2025-52533, CVE-2023-31364, CVE-2025-29950, CVE-2024-36355, CVE-2025-29939, CVE-2025-0012, CVE-2023-20539, CVE-2025-52536, CVE-2024-21961, CVE-2025-29948, CVE-2024-21953, CVE-2025-0027, CVE-2025-29952, CVE-2025-52534, CVE-2025-48517, CVE-2025-0031, CVE-2024-36310, CVE-2025-29946, CVE-2025-48514, CVE-2025-0029, CVE-2025-48509.

R13

1. [Feature] Optimize PCIe inventory display in WebBMC.

R12

1. [Feature] Update AGESA 1.0.0.5.
2. [Security] CVE-2024-13176

R11

1. [Feature] Update AGESA 1.0.0.5.
2. [Security] CVE-2024-13176

R10

1. [Feature] Optimize PCIe compatibility.

R09

1. [Feature] Update Inventory v16.
2. [Feature] Optimize PCIe compatibility.
3. [Fix] Optimize LAN controller BIOS item.

R08

1. [Feature] Update DDR manufacturer information.
 2. [Feature] Add Microsoft Option ROM UEFI CA 2023 key.
 3. [Feature] Enhance SMBIOS type9.
 4. [Feature] Enhance Redfish.
-

BIOS Release Notes

R07

- 1.[Feature] Update AGESA 1.0.0.4.
 - 2.[Security] CVE-2023-6237, CVE-2024-6119, CVE-2024-7344.
-

R06

1. [Feature] Update for PCIe NVMe compatibility.
 2. [Fix] Update for Setup Menu PCIe OPROM item typo.
 3. [Fix] Fixed console shows abnormal log on POST.
 4. [Feature] Enhanced SMBIOS type32 information.
 5. [Feature] Optimize PCIe compatability.
 6. [Feature] Optimize USB compatibility.
-

R05

- 1.[Fix] Fix PCIE compatibility when install GPU card.
-

R04

1. [Feature] Added G494-ZU0-AAP1-000, TO25-ZU4-AA01-000, TO25-ZU5-AA01-000 system support.
 2. [Feature] Update Inventory v13.
-

R03

1. [Fix] SCE tool import/export issue.
 2. [Fix] Fix Redfish sends data twice after the system has completed booting.
 3. [Feature] Adjust the maximum speed limit during automatic memory training.
 4. [Feature] Add support for PCIe Re-Sizeable BAR functionality.
-

R02

- 1.[Feature] Update AGESA 1.0.0.3.
 - 2.[Feature] Support DDR speed up to 6400, but it requires manual adjustment in the BIOS settings.
UMC Common Options => Enforce POR => Accept => Memory Target Speed set [DDR6400]
Note: The maximum supported speed is based on product specifications.
 - 3.[Fix] Fix the issue where NVMe speed is reduced to Gen4 after a hot plug.
 - 4.[Fix] Fix the issue where SEL reports incorrect DDR channel information when associated with CPU1.
 - 5.[Fix] Fix the issue where the system ready to boot process gets stuck when the BMC is unresponsive.
-

R01

BIOS Release Notes

1. [Feature] First release.
